


*FIG. 1*



+

2/12




FIG. 2A




FIG. 3




FIG. 4

+

+

3/12




FIG. 5




FIG. 6






FIG. 7

+



+

4/12



+

5/12



6/12




FIG. 12




FIG. 13

7/12

EFFECT OF CABLE CURVATURE ON CABLE POSITION, 5 FT. EXACT DEPTH




FIG. 14




FIG. 15

8/12




FIG. 16




FIG. 17



9/12




FIG. 18




FIG. 19

10/12




FIG.20




FIG.21

DEPTH MEASUREMENT ERRORS NEAR CABLE BEND, 5 FT. CABLE DEPTH




FIG. 22

DEPTH MEASUREMENT ERRORS NEAR CABLE BEND, 5 FT. CABLE DEPTH




FIG. 23

12/12




FIG.24




FIG.25